



MHA CTM-Vocational Hub

April, 2021

Water Damaged Roof Causing Leakage



Building Leaked Ceiling



Roof
Water
Damage



Courtyard Ceiling



Roof
Water
Damage

Kitchen Ceiling

Roof
Water
Damage



Classrooms Leakage

Roof
Water
Damage



The Hall



Two Buildings



Annex



Vocational

Leaked
Roof